

For your safety, please read the following before using.

- Suggest to connect, install, and set up by professional technicians.
- Avoid to use magnetically conductive components in working environment.
- Avoid piston and magnet of cylinder spin to cause inaccurate.
- Do not use corrosive or flammable gas or liquid with this product.
- Do not drop, hit or allow excessive shock. Even if switch body appears undamaged, internal components may be broken and can cause malfunction.
- Turn power off before connecting wiring. Wrong wiring or short circuit will damage and / or cause malfunction.
- This product is not explosion-proof rated. Do not use in atmosphere containing flammable or explosive gases.
- Wiring for pressure sensor should avoid power source line and high voltage line. If use in the same circuit, noise may cause malfunction.
- Sensors at end-of-life must be disposed of in accordance with E-Waste regulations of the country/region, NOT disposed of with regular garbage.

A. SPECIFICATIONS

MODEL	RLZ-□040	
Measuring Range	40 mm, ± 1 mm	
Power Supply Voltage	15 ~ 30 V DC, Ripple (P-P) ≤ 10 %	
Current Consumption	≤ 15 mA (with no load)	
Displacement Resolution ※1	0.001 mm	
Linearity Error ※1	± 0.2 mm @ 25 °C	
Repeatability ※1	± 0.01 mm @ 25 °C	
Sampling Time	≤ 0.3 ms	
Analog Voltage Output ※2	Voltage Output : 0 ~ 10 V Min. Load Impedance : 2 KΩ Linearity : ± 0.05 % F.S. @ 25 °C Sensitivity : 0.25 mV/μm	
Analog Current Output ※2	Current Output : 4 ~ 20 mA Max. Load Impedance : 500 Ω Linearity : ± 0.05 % F.S. @ 25 °C Sensitivity : 0.4 μA/μm	
Magnetic Field Strength ※1 ※3	20 ~ 200 Gauss	
Environment	Enclosure	IP69 IEC 60529
	Ambient Temp. Range	Operation : 0 ~ 50 °C, Storage : -10 ~ 60 °C (No condensation or freezing)
	Ambient Humidity Range	Operation / Storage : 35 ~ 85 % RH (No condensation)
	Withstand Voltage	1000 V AC in 1-min (between case and lead wire)
	Insulation Resistance	≥ 50 MΩ (at 500 V DC, between case and lead wire)
Shock ※4		30 G
	Vibration ※5	10 G
Lead Wire	Ø2.9 PUR - 26 AWG (0.15mm ²) - 3 cores	
Weight (With 2 meter lead wire)	Approx. 33 g (RLZ-C040) ; Approx. 37 g (RLZ-T040)	
Protection Circuit	Power Source Reverse polarity, Surge Suppression	

NOTE

- Measuring standard target : Ø15.5 × Ø8 × 5t (The movement of anisotropy rubber magnet and piston are from same direction.)
- Only one of analog output can be selected while setting.
- The difference of magnetism, environment, and interference of magnetic field can cause the deviation of measurement.
- Sin wave / X, Y, Z 3 directions / 3 times each direction / 11 ms each time.
- Double amplitude 1.5 mm or 10 G / 10 Hz ~ 55 Hz ~ 10 Hz (Sweep 1 min) / X, Y, Z 3 directions / 2 hours each time.

B. ORDERING INFORMATION


RLZ - C040 - 2M

Cylinder Type
C : C slot
T : T slot

Cable Length / Connector
2M : L = 2000mm
QD : With M8 3Pin male connector


Measuring Range
040 : 40 mm

C. OUTPUT CIRCUIT WIRING DIAGRAMS





D. ANALOG OUTPUT FUNCTION

- Analog voltage / current output can be switched.
- Analog output can be inverted.



E. DIMENSIONS




No.	Content
1	Mode Indicator
2	Information Indicator
3	Setting button
4	Mounting screw, Hexagon wrench (2.0 mm)

QD PINOUT

Unit : mm

F. INSTALLATION




G. LED INDICATOR DESCRIPTION


Mode	Mode Indicator	Information Indicator	Description
Measuring Mode	N	G	Within the setting range
		N	Within the measuring range, but outside the setting range.
		R	Outside the measuring range
Setting Mode	R/B	N	Setting mode
Measuring Range Setting	B	B	POINT 1 setting
		G	POINT 2 setting
		R	Not available to set the measuring range.
Analog Output Setting	R	G	Analog voltage output mode
		B	Analog current output mode
Invert Analog Output Setting	G	G	Analog output setting (0 ~ 10 V / 4 ~ 20 mA)
		B	Analog output setting (10 ~ 0 V / 20 ~ 4 mA)
Restore Factory Setting	R	R	Enter restore factory mode
		G	Turn on restore factory function
Data Saving	W	W	Do not power off during data saving.


※ N : LED off, G : Green, B : Blue, R : Red, W : White, O : LED flashing, R/B : Red / Blue alternately flash


H. OPERATING PROCEDURES



I. OPERATION DEFINITION

This sensor uses capacitive setting button  which is based on press times and press period to operate.


- Press  1 time (press < 0.5 s) : confirm / save





- Press  2 times (press / release < 0.5 s) : switch the options



- Long press  0.5 ~ 5 s : cancel







- Press briefly  and long press  : enter setting mode











J. OPERATION INSTRUCTION - FOUR KINDS OF SETTING MODE

1. Measuring Range Setting





- Step 1 : Press briefly and long press  until red and blue lights flash alternately to enter setting mode.
- Step 2 : Press  1 times, then blue mode/information indicators light up to enter measuring range setting.
- Step 3 : Push the piston to the POINT 1 of the measuring range, then press  1 time to complete POINT 1. Red information indicator lights up. (※ 1.2)
- Step 4 : Push the piston to the POINT 2 of the measuring range, then press  1 time to complete POINT 2.
- Step 5 : White mode/information indicators flash after complete setting.

- Note ※ 1 · In below cases, measuring points cannot be set.
- 1.1 · Outside the measuring range. Red information indicator lights up.
 - 1.2 · The distance of start point and end point is less than 1 mm. Red information indicator lights up.
- ※ 2 · The default setting is the maximum measuring range.
- ※ 3 · After 60 seconds of inactivity, the product returns to measuring mode automatically.
- ※ 4 · Reset the measuring range by repeating Step 1 to Step 5.




LED Indicator Description	
	: LED off
	: Blue
	: Green
	: Red
	: White
	: Red / Blue alternating flashing
	: LED flashing





2. Analog Voltage / Current Output Setting

- Step 1 : Press briefly and long press  until red and blue lights flash alternately to enter setting mode.
- Step 2 : Press  2 times, then red mode indicator lights up to enter analog voltage / current output setting.
- Step 3 : Press  2 times for switching analog voltage output or analog current output.
Green information indicator : analog voltage output
Blue information indicator : analog current output
- Step 4 : Press  1 time to complete analog voltage / current output setting.
- Step 5 : White mode/information indicators flash after complete setting.


- Note ※ 1 · After 30 seconds of inactivity, the product returns to measuring mode automatically.
- ※ 2 · Switch analog output again by repeating Step 1 to Step 5.







3. Invert Analog Output Setting

- Step 1 : Press briefly and long press  until red and blue lights flash alternately to enter setting mode.
- Step 2 : Press  3 times, then green mode indicator lights up to enter invert analog output setting.
- Step 3 : Press  2 times for inverting analog output value.
Green information indicator : analog output 4 ~ 20 mA / 0 ~ 10 V.
Blue information indicator : analog output 20 ~ 4 mA / 10 ~ 0 V.
- Step 4 : Press  1 time to complete invert analog output setting.
- Step 5 : White mode/information indicators flash after complete setting.

- Note ※ 1 · After 30 seconds of inactivity, the product returns to measuring mode automatically.
- ※ 2 · Switch analog output again by repeating Step 1 to Step 5.



4. Restore Factory Setting

- Step 1 : Press briefly and long press  until red and blue lights flash alternately to enter setting mode.
- Step 2 : Press  4 times, then red mode indicator flashes to enter restore factory setting.
- Step 3 : Press  2 times, then red mode indicator and green information indicator flash to turn on restore factory function.
- Step 4 : Press  1 time to restore factory setting value.
- Step 5 : White mode/information indicators flash after complete setting.

- Note ※ 1 · Return to measuring mode if operate wrongly.
- ※ 2 · After 30 seconds of inactivity, the product returns to measuring mode automatically.
- ※ 3 · Switch analog output again by repeating Step 1 to Step 5.

