



2017/09/27

R*S Series Sensors Discontinued Notification

Thank you for supporting Mindman products.
We apologize for any potential inconvenience.
Thank you for your cooperation.
The following products will be discontinued.

Model

RCS, RNS, RPS

Reason

The R*S series sensors are using screws to fix in the right place, but the sensors sometimes malfunction when the tightening torque is too high.

Alternatives

The R*M series sensors are going to replace R*S series sensors.

Discontinued RCS/RNS/RPS	Alternatives RCM/RDM/RNM/RPM
	

Effective Date

After R*S series sensors run out of stocks.

Other

If there is any question, please contact our sale department.