

February 29<sup>th</sup>, 2024

## MCQV3 / MCQI3-Ø63

### Repair kits change Notification

Thank you for supporting Mindman products. The design change will apply to the following models. Sorry for any inconvenience that may occur. Kindly understand and cooperate.

1. Model series

MCQV3 / MCQI3-Ø63

2. Design change reason

Change the repair kits content due to the front cap design modification.


3. Change descriptions

See next page.





4. Effective date

Immediately.

5. If there are any questions, please contact our sales department.



Change descriptions:

Before	After
 <p>1. Rod sealing</p>	 <p>1. Rod sealing 2. Cushion pads *2pcs (for piston) <b>Newly Added.</b></p>
<p>Profile difference</p>  <p>Washer+ORA</p>	<p>Profile difference</p>  <p>UB Rod sealing</p>