




2016/06/21

「MCMA/MCMB*/MCKMB – Ø32 **Port Hole Change Notification**」

Thank you for supporting Mindman products.

We apologize for any inconvenience may occur.

Thank you for your cooperation.

The design change will apply to the following products.

1. Model series

MCMA/MCMB*/MCKMB – Ø32

2. Design change reason

The original size design of port hole will cause piston speed exceed the max limit speed easily. Using a piston with speed out of limit range will cause cylinder lifetime reduced. So we reduce the port hole size to prevent this problem occur.

3. Design change details

Change MCMA/MCMB*/MCKMB – Ø32 port hole size from Ø3.5 to Ø2.1 .

4. Effective Date

Start from 2016/07/01 .

5. If you have any question, please contact our sales department.