



Sep. 23rd, 2020

MCKC series

Piston Rod Surface Treatment Change Notification

Thank you for supporting Mindman products. MCKC series will have design changes below. We are sorry about any inconvenience would cause.

1. Affected Model(s)

MCKC-Ø12/Ø16/Ø20/Ø25/Ø32/Ø40

2. Change Reason(s)

For increasing product performance.

3. Change Content(s)

Surface treatment changed.

Surface color of piston rod: metal silver→bright black



4. Effective Date

Start immediately after run out of old nickel plated rods.

5. Other(s)

If there is any further question, please contact our sales department.