

Nov. 26<sup>th</sup>, 2020

## MCM\*/MCKM\*/MCBMI/MGT\*/MSLL-Ø 16~Ø 40 Adjustable Cushion Type Cylinders Change Port Hole Notification

Thank you for supporting Mindman products. The design change will apply to the following products. We apologize for any inconvenience that may occur. Thank you for your cooperation.

### 1. Model series



MCMA/MB/MI、MCMBRA/RB、MCMBL、MCKMB/KMI、MCBMI、MGTB/TU/TK、MSLL

### 2. Design change reason

Change design of port hole to optimize product performance.

**P.S. Be sure to install speed controller on the cylinder and adjust speed according to the specified speed range in the catalog.**

### 3. Changed contents

Before (For example: MCMB-Ø 25-A series)	After (For example: MCMB-Ø 25-A series)
Smaller port orifice	Full port orifice
	

### 4. Effective date

It will not affect the usage, and replace sequentially.

### 5. If there is any question, please contact our sales department.